MAI ERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

DPM2268

DATEC	F PREP.
-------	---------

August 1977

Section I

MANUFACTURER'S NAME

Koppers Company, Inc.

STREET ADDRESS

5431 District Blvd.

CITY, STATE, AND ZIP CODE

Vernon, CA 90040

EMERGENCY TELEPHONE NO.

213 - 726-8666

PRODUCT CLASS

Primer, Synthetic, Rust Inhibiting

MANUFACTURERS CODE IDENTIFICATION

P-380-66

TRADE NAME

TT-P-664

Section II — HAZ	ARDOUS	NGREDIE	NTS		· · ·	
INGREDIENT	PERCENT	PPM	LV mg/Mª	LEL	VAPOR PRESSURE	
Zinc Chromate Ethyl Benzene Isobutanol VM&P - Naphtha XyleneS0-1200 Lead in Drier	4.00 3.00 4.60 21.30 .14 10.80 .13	- 100 100 400 100 150	0.1 435 300 1800 435 - 0.2	1.0 1.7 1.0 1.0 1.2	10mm/25.9°C 10mm/31.7°C 15mm/100°F 10mm/32.1°C 36mm/100°F 1mm/9.75°C	
Section III — PHYSICAL DATA						
BOILING RANGE 190-420°F EVAPORATION RATE FASTER X SLOWER, THAN ETHER	VAPOR DE PERCENT VOLATII BY VOLUME	بميــــ	WEIGHT PER GALLON	LIGHTER	.THANAIR	

Section IV — FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY

Flammable - Red Label

FLASH POINT 50°F TCC

LEL 1.00

EXTINGUISHING MEDIA

Carbon dioxide, foam or dry chemical

UNUSUAL FIRE AND EXPLOSION HAZARON

May form explosive vapor mixture between upper and lower explosive limits. Do not use welding or cutting torch on or near drum. (even empty).

SPECIAL FIRE FIGHTING PROCEDURES

Do not use water

Section V — HEALTH HAZARD DATA
THRESHOLDLIMIT VALUE (Zinc Chromate) Not assigned, estimate .1 mg/m ³
Headache, nausea, moderately irritating to eyes and skin
EMERGENCY AND FIRST AID PROCEDURES
Remove victims from vapors - restore breathing if necessary. Remove from skin with soap and water. Flush eyes with water.
Section VI — REACTIVITY DATA
STABILITY UNSTABLE STABLE CONDITIONS TO AVOID INCOMPATABILITY (Materials to avoid) N/A HAZARDOUS DECOMPOSITION PRODUCTS Co, CO, aldehudes, and other organics, lead oxide, chromic oxide
HAZARDOUS POLYMERIZATION MAY OCCUR WILL NOT OCCUR CONDITIONS TO AVOID
Section VII — SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CAȘE MATERIAL IS RELEASED OR SPILLED
Remove sources of ignition. Apply sawdust or other absorbent material. Keep from spreading waste disposal METHOD
Put in metal container and seal for disposal
Section VIII — SPECIAL PROTECTION INFORMATION
For confined areas use Bureau of Mines Respiratory Device Approval 25 B-13 BM2304 Face Piece BM2304 Cartridge
BM2313 Filters BM2313 Filter Clips Ventilation should be adequate to keep lower level below LEL
PROTECTIVE GLOVES Rubber EYE PROTECTION Safety OTHER PROTECTIVE EQUIPMENT Rubber soles must be worn (no static electricity)
Section IX — SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING
Flammable - store away from open flame and high heat
Do not take internally - avoid prolonged contact with skin